





## Manually Changing Satellite Correction Settings

Precision-IQ™ - XCN050, XCN750, XCN2050

1. From the Precision-IQ Home screen, tap the **GNSS** tile:



2. On the GNSS screen, tap the **Edit** button:



3. On the *GNSS: Edit* screen, tap the **Setup** tab, and then tap **Correction Satellite Selection**:




4. From the *Correction Satellite Selection* dialog, tap **WAAS 135 GALAXY XV** (also known as *WAAS 135*):

Changes to WAAS Satellite configuration - May 2022



CHESLEY | LUCKNOW | MOUNT FOREST | WALTON



**Note:** Users can enter the custom PRN number if this user interface is not present in your version of Precision-IQ. Or recommend updating system firmware to this latest version in order to get all the latest product improvements.

5. The *GNSS: Edit* screen will update to show the new selection. Tap **Save**:

